Setting:

The proposed work is on a grade two listed part timber framed and part masonary extensive farmhouse.

The original farmhouse and dates from the fifteenth century and there has been further extensions in the 16th century and a further Larger modernisation and extension in the 18th century. The farmhouse and garden stands midway along Doggets Chase surrounded by arable farmland and a scattering of farm labourers dwellings.

Heritage asset affected by the proposal:

Doggetts Farmhouse. Doggetts Chase. Rochford. Essex. SS4 3RN.

Development:

The work comprises of the removal of a fairly dilapidated single storey 1970's lean too conservatory with polycarbonate roof and the construction of a new timber conservatory on a slightly extended footprint. The new footprint will exactly replicate the footprint of a previous 18th century conservatory that was demolished to make way for the one that exists at present. The client wishes the conservatory to be made from oak with traditional style lambs tongue flush top hung casements to the front and side facades of the conservatory and a natural slate roof with three conservation style roof lights.

Assessment of impact:



Setting:

The proposed work is on a grade two listed part timber framed and part masonary extensive farmhouse.

The original farmhouse and dates from the fifteenth century and there has been further extensions in the 16th century and a further Larger modernisation and extension in the 18th century. The farmhouse and garden stands midway along Doggets Chase surrounded by arable farmland and a scattering of farm labourers dwellings.

Heritage asset affected by the proposal:

Doggetts Farmhouse. Doggetts Chase. Rochford. Essex. SS4 3RN.

Development:

The work comprises of the removal of a fairly dilapidated single storey 1970's lean too conservatory with polycarbonate roof and the construction of a new timber conservatory on a slightly extended footprint. The new footprint will exactly replicate the footprint of a previous 18th century conservatory that was demolished to make way for the one that exists at present. The client wishes the conservatory to be made from oak with traditional style lambs tongue flush top hung casements to the front and side facades of the conservatory and a natural slate roof with three conservation style roof lights.

Assessment of impact:



Setting:

The proposed work is on a grade two listed part timber framed and part masonary extensive farmhouse.

The original farmhouse and dates from the fifteenth century and there has been further extensions in the 16th century and a further Larger modernisation and extension in the 18th century. The farmhouse and garden stands midway along Doggets Chase surrounded by arable farmland and a scattering of farm labourers dwellings.

Heritage asset affected by the proposal:

Doggetts Farmhouse. Doggetts Chase. Rochford. Essex. SS4 3RN.

Development:

The work comprises of the removal of a fairly dilapidated single storey 1970's lean too conservatory with polycarbonate roof and the construction of a new timber conservatory on a slightly extended footprint. The new footprint will exactly replicate the footprint of a previous 18th century conservatory that was demolished to make way for the one that exists at present. The client wishes the conservatory to be made from oak with traditional style lambs tongue flush top hung casements to the front and side facades of the conservatory and a natural slate roof with three conservation style roof lights.

Assessment of impact:



Setting:

The proposed work is on a grade two listed part timber framed and part masonary extensive farmhouse.

The original farmhouse and dates from the fifteenth century and there has been further extensions in the 16th century and a further Larger modernisation and extension in the 18th century. The farmhouse and garden stands midway along Doggets Chase surrounded by arable farmland and a scattering of farm labourers dwellings.

Heritage asset affected by the proposal:

Doggetts Farmhouse. Doggetts Chase. Rochford. Essex. SS4 3RN.

Development:

The work comprises of the removal of a fairly dilapidated single storey 1970's lean too conservatory with polycarbonate roof and the construction of a new timber conservatory on a slightly extended footprint. The new footprint will exactly replicate the footprint of a previous 18th century conservatory that was demolished to make way for the one that exists at present. The client wishes the conservatory to be made from oak with traditional style lambs tongue flush top hung casements to the front and side facades of the conservatory and a natural slate roof with three conservation style roof lights.

Assessment of impact:

